

NOTES:
1. SYMBOLS ARE ELECTRICAL REPRESENTATION ONLY.
2. TO BE WIRED IN ACCORDANCE WITH NATIONAL ELECTRIC N.E.C. AND LOCAL CODES.
3. USE COPPER CONDUCTORS ONLY. USE CONDUCTORS SUITABLE FOR AT LEAST 75°C (167°F).
4. CHECK ALL ELECTRICAL CONNECTIONS INSIDE CONTROL BOX FOR TIGHTNESS.

REFERENCE WIRING HARNESS 2422, 2423, 2486, 2842, 2892, & 2894

ICE ENERGY®

Ice Bear® 30 Unit

CoolData® Controller, K2 Electrical Schematic

Ref. # 3037 Rev A